

# Moisture Infiltration/ Suspected Fungal Growth Assessments



## Preliminary Assessments May Address:

### Initial documentation of:

- Existing Conditions
- Baseline Moisture Levels  
(Impacted Versus Non-impacted Areas)
- Relative Humidity and Temperature
- Boroscope Imagery
- Preliminary Source Determination
- Preliminary Magnitude Determination
- Final Report
- Scope of Work (Phase II Level of Effort)
- Collaborative Development with  
Mechanical, Building Envelope Engineers
- Treatment Oversight
- Post Treatment Air Sampling
- Closure Documentation

CONNOR

**Michael S. Spangler • Operations Manager**

443.322.1203 (O) 410.296.3419 (F)

[mspangler@connorsolutions.com](mailto:mspangler@connorsolutions.com)

Bare Hills Business Center

1421 Clarkview Road • Suite 100 • Baltimore, MD 21209-2187



NAT-19978-1